


Ikelite Pro Compass

instruction manual



LINE OF SIGHT_____

The lubber line should always be pointed towards your destination.

NORTH INDICATOR_____

Moves in accordance to magnetic North. North Indicator points to the direct-reading degree scale on the compass.

BEZEL MARKINGS_____

Allows comparison between your desired course heading and actual course. Keep the North Indicator aligned with the luminous bezel markings.

USING THE PRO COMPASS

VISUAL SIGHTING_____

Aim the lubber line towards your destination. Then rotate the bezel to align the Bezel Parallel Markings over the North Indicator. Follow the Lubber Line while keeping the North Indicator between the Bezel Parallel Markings.

For your reciprocal course, align the North Indicator with the luminous mark opposite the Parallel Markings and again follow the Lubber Line.

DEGREE SIGHTING_____

Counter-clockwise degree markings allow direct reading of the compass for following a given course.

Align both the North Indicator and the Bezel Parallel Markings at the given degree reading. Maintain alignment while following the Lubber Line.

Protect the compass from the HEAT & SUN as both could cause damage to the capsule.

MAINTENANCE

1. Rinse well after using.
2. Occasionally remove the base plate and push out the capsule and bezel for a thorough cleaning.
3. No lubrication is needed.
NEVER USE SPRAY LUBRICANT.
4. Wearing compass next to a metallic gauge could affect accuracy.

Ikelite Limited Warranty

All Ikelite products are warranted against any manufacturing defects for a period of one (1) year from the date of purchase. Defective products should be returned prepaid to Ikelite. Ikelite will, at its discretion, repair or replace such products, and will return to customer prepaid. All other claims, of any nature, including but not limited to bulb failure are not covered. Except as mentioned above, no other warranty expressed or implied, applies to this Ikelite product.

Returning Products for Service

Ikelite is most interested in performing any service to assure that all products perform as intended. For repair or service, return the product to the address below with your name, address, phone number and a brief description of the problem. Evidence of purchase date must be provided to obtain warranty service.

Ikelite Underwater Systems

50 W 33rd Street
PO Box 88100
Indianapolis, IN 46208 USA

317-923-4523

email: ikelite@ikelite.com
www.ikelite.com